

Digital Panel Meter

PICA-T

A compact 4 digit scalable AC/DC Voltage and Current meter with wide-range power supply.

DESCRIPTION

INDICATOR for:

- PT100 SENSOR
- THERMOCOUPLE TYPE J, K, T and N

Fully programmable panel meter for temperature measurement in $^\circ C$ or $^\circ F$ using Pt100 sensor or thermocouple type J, K, T and N.


Configurable indication in °C or tenths of °C for Pt100 sensor.

Controlled by three buttons situated on the bottom of the display.

DIMENSIONS AND MOUNTING

Dimensions Panel Cutout Weight	
Case Material	Polycarbonate s/ UL 94 V-0

Instruments include a sealing gasket and a fixing clip for front and rear panel installation.



TECHNICAL SPECIFICATIONS

INPUT:
Pt100 Measurement Current 1mA Pt100 Linearization IEC 60751 Pt100 α Coefficient 0.00385 Pt100 Maximum Wire Resistance 40Ω (balanced) Thermocouple Cold Junction Compensation Range -10°C a 60°C
ACCURACY at 23°C ±5°C
Pt100 (1°) $\pm (0.2\% \text{ rdg} + 1°C) / \pm (0.2\% \text{ rdg} + 2°F)$
$\begin{array}{c} t <-50^{\circ}\text{C}/-58^{\circ}\text{F} \Rightarrow \pm(1\%\text{rdg}+1^{\circ}\text{C}) \ / \ \pm(1\%\text{rdg}+2^{\circ}\text{F}) \\ \text{Pt100} \ (0.1^{\circ}) \ \dots \ \pm(0.2\% \ \text{rdg} + 0.4^{\circ}\text{C}) \ / \ \pm(0.2\% \ \text{rdg} + 0.7^{\circ}\text{F}) \\ t <-50.0^{\circ}\text{C}/-58.0^{\circ}\text{F} \Rightarrow \pm(1\%\text{rdg}+0.4^{\circ}\text{C}) \ / \ \pm(1\%\text{rdg}+0.7^{\circ}\text{F}) \end{array}$
Temperature Coefficient
POWER SUPPLY AND FUSES (DIN 41661, not included)
PICA-T:
CONVERSION
Technique Sigma-Delta Resolution ±15 bits Conversion Rate 20/s
DISPLAY
Type
ENVIRONMENTAL CONDITIONS
Operating Temperature -10°C to +60°C Storage Temperature -25°C to +85°C Relative Humidity (non condensing) <95% @ 40°C


ORDERING CODES PICA -T -X Input Type: Supply Voltage: 85-265V AC 50/60Hz and 100-300V DC 0 21-53V AC 50/60Hz and 11-70V DC



1/32 DIN PT100 / Thermocouple Panel Meter


CONFIGURATION

Resolution	Pt100	TC "J"	TC "K"	TC "T"	TC "N"
1°	-200 to 800°C -328 to 1472°F		-200 to 1250°C -328 to 2282°F	-200 to 400°C -328 to 752°F	-200 to 1250°C -328 to 2282°F
0.1°	-199.9 to 800°C -199.9 to 999.9°F	-	-	-	-



CONNECTIONS

Instruments include a sealing gasket and a fixing clip for front and rear panel installation. These meters have detachable plug-in connectors. Wires are held in place with spring clamps. A special displacement tool is included to help you connect your wiring to the clamps.



In order to guarantee electromagnetic compatibility, the following guidelines for cable wiring must be followed:

wiring must be followed: Power supply wires must be separated from signal wires. Never run power and signal wires in the same conduit. Use shielded cable for signal wiring and connect

Use shielded cable for signal wiring and connect shield to ground.

Cable section must be ≥0.25mm2

INSTALLATION

Where the unit is permanently connected to the main supply and to meet the requirements of EN61010-1 Directive, it is obligatory to install a circuit breaker device easy reachable to the operator and clearly marked as a protection device.

CLEANING: Front cover should be cleaned only with a soft cloth soaked in neutral soap product. **DO NOT USE SOLVENTS.**

WARRANTY

All products are warranted against defective material and workmanship for a period of two years from acquisition date.

If a product appears to have a defect or fails during the normal use within warranty period, please contact the distributor from whom you purchased the product to be given proper instructions.

This warranty does not apply to defects resulting from action of the customer such as mishandling or improper interfacing.

The liability under this warranty shall extend only to the repair of the instrument; no responsibility is assumed by the manufacturer for any damage which may result from its use.

www.london-electronics.com

PICA_E_datasheet-manual_rev1

+44

+44 (0)1767 626444



London Electronics Ltd, Thorncote Road, Near Sandy, Bedfordshire, SG19 1PU, England

